Operating Manager

Sales Department

Parts Department

Service Department

Service Bulletin

Date: March 2002

Bulletin No: 16 001 02 (010)

BMW Motorcycles

Subject: Charcoal canister inspection - F 650 CS

Details: On early production examples of the F 650 CS model, the possibility

exists that a plastic protective cap, used to preserve the integrity of the charcoal canister during shipping, was not removed during final motorcycle assembly. If the cap is not removed, this could lead, in some cir-

cumstances, to a rough running engine.

Aftersales During the set-up and PDI, or a routine service, inspect the charcoal canister and remove the cap if necessary.

The photo below illustrates the charcoal canister with the plastic cap in place.



Warranty Information:

Removal of this plastic cap is to be considered as part of the set-up and PDI of this model.

ANT.

Thomas J. Plucinsky
General Manager
BMW Motorcycles



Pat Raymond
Service and Technical Manager
(201) 307 4261
pat.raymond@bmwna.com

