	Service Bulletin Page 1 of 1		
	Date: January 2004 Bulletin No: 06 001 04 (001)		
BMW Motorrad USA			
	Subject:	BMW Motorrad Diagnostic System CD 13.1 BMW Group Tester One (GT-1)	
Operating Manager		The BMW Motorrad Diagnostic System CD 13.1 is now available and will be forwarded to each retailer in the very near future.	
Sales Department		The BMW Motorrad Diagnostic System CD 13.1 supercedes CD13.0.	
Accessory Department	Contents: The Diagnostic System CD 13.1 includes the following new information:		
Parts Department		Correction of communication fault with ABS2 control unit (applies only to the GT-1 application).	
Service Department	Full functionality for the BMW MoDiTeC and the BMW GT-1.		loDiTeC and the BMW GT-1.
Ref.: 00 73/2003		CD 13.1 will be sent to each retailer as part of the automatic tool ship- ment program.	
	Contact:	Pat Raymond Service and Technical Manager BMW Motorrad USA	(201) 307 4261 pat.raymond@bmwna.com

